

# TEST REPORT

The report shall not be reproduced without written approval from Intertek  
The results relate only to the item tested.

Report no.: BKKH22003511

**Applicant:** SALAMANDER JEWELRY CO., LTD  
128/1 MOO7, SOI WAT NAKHON CHUENCHUM, PHUTTHAMONTHON  
SAI 4 ROAD, TAMBON KRATUMLOM, AMPUR SAMPRAN, NAKORN  
PATHOM 73220 THAILAND  
ATTN: K. JUTHA

Issued Date: Apr 01, 2022

### Sample Submitted:

Quantity of sample: Three (3) set  
Sample description: Mix gold metal part  
Date sample received: March 21, 2022  
Date information submitted: March 30, 2022

### Client Information:

Sample Name: All Gold (yellow gold, rose gold and white gold)



\*\*\*\*\*

### Test conducted:

As requested by the applicant, for details please refer to attached page(s)

\*\*\*\*\*

### Conclusion:

<u>Tested samples</u>	<u>Client's Requirement</u>	<u>Result</u>
Submitted sample	Nickel release content requirement in Annex XVII Item 27 of the REACH Regulation (EC) No.1907/2006 & Amendment No.552/2009 (Formerly known as Directive 94/27/EC and 2004/96/EC)	Pass

Comment: According to the standard, individual testing should be performed, however, as request by the applicant, mix testing has been conducted on the submitted samples.

\*\*\*\*\*

For and on behalf of :  
Intertek Testing Services (Thailand) Ltd.,  
Hardlines Laboratory

-----  
Ladtaka Wongwiboornporn  
Operation Manager  
Hardlines Department



## TEST REPORT

The report shall not be reproduced without written approval from Intertek  
The results relate only to the item tested.

Report no.: BKKH22003511

Test conducted:

- 1 Release of Nickel for Direct Prolonged Skin Contact Item  
As per EN1811: 2011 + A1: 2015

<u>Tested component</u>	<u>Trial</u>	<u>Sample area (cm<sup>2</sup>)</u>	<u>Volume of Test solution (ml)</u>	<u>Result Δ (μg/cm<sup>2</sup>/week)</u>
Submitted sample	1	1.59	1.59	<0.01
	2	1.59	1.59	<0.01
	3	1.59	1.59	<0.01

Remark : < = Less than  
μg = Microgram  
cm<sup>2</sup> = Square centimeter

Requirement: 0.5 μg/cm<sup>2</sup>/week

Remark: Δ = According to EN 1811: 2011 + A1: 2015, compliance decision was made based on the following rules.

<u>Result</u>	<u>Interpretation</u>
< 0.88	Compliance (Pass)
≥ 0.88	Non-compliance (Fail)

Tested component: Mix gold metal part

Testing period: March 21, 2022 to April 01, 2022

\*\*\*\*\* E N D \*\*\*\*\*/WB/NK

*Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: <http://www.intertek.com/terms/>. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk. This report shall not be reproduced, except in full.*