

To protect the privacy of customers or suppliers of Salamander Jewelry. We erased their address from this document.

TEST REPORT

Report No. 010222120052

DATED: 10 JANUARY 2023

Client : SALAMANDER JEWELRY CO., LTD.
128/1 MOO 7, SOI WAT NAKHON CHUENCHUM,
PHUTTHAMONTHON SAI 4 RD,
TAMBON KRATUMLOM, AMPUR SAMPRAN,
NAKHON PATHOM 73220, THAILAND

Buyer : /

Sample Description : LEATHER

Item No. : /

SKU No. : /

Model / Style : /

Manufacturer : /

Country of Origin : /

Country of Destination : /

Test Sample Received : RECEIVED ON 03/01/2023

Test Period : FROM 03/01/2023 TO 10/01/2023

TEST REQUESTED	CONCLUSION	REMARK
REACH REGULATION (EC) NO 1907/2006, ANNEX XVII ENTRY 63 – LEAD	PASS	-

To protect the privacy of customers or suppliers of Salamander Jewelry. We erased their address from this document.