To protect the privacy of customers or suppliers of Salamander Jewelry. We erased their address from this document.

COMMODITY: Stainless Steel Cold Finished Round Bar

STEEL GRADE: 304

1000

698

SUPPLY CONDITION: CD

62

98

CERTIFICATE NO: A2107310508								DOC No.:									DATE OF ISSUE: 2021/0						//31			
ID N	o Thick (Dia) Pcs Wt					Chemical Composition(wt%)												Mechanical Property								
		(mm)			(kg)	C v1000	Si	Mn v100	P ×1000	S v1000	Ni v100	Cr x100	Mo x100	Cu v100	N x10000				TS N/mm2	YS N/mm2	EL %	RA	HRB	HB	HRC	
	1	_				X1000	X100	X100	X1000	X1000			X100	X100	X10000				IN/ IIIIIIZ	N/IIIIIZ	70	70				
	Min										800	1800											, !	, ,		

53

2000

1819

Total:

Spec

6K072205

1004 1004

59

200

182

45

29

30

1050

810

100



776

649

39

TOLERANCE: h9 LENGTH TOLERANCE: 0-50 This inspection certificate is issued according to EN 10204 2.2 SUPPLY CONDITION: Remark: We have the following certifications A:Annealed Melted and poured in Taiwan Improved machining. 1.ISO9001:2015 Quality Management System B:Shot Blasted Solution annealed treatment: Acc. to ASTM A484. 2.ISO/IEC 17025:2017 Laboratory Management System C:As Casted Micro structure: good., Grain size: Acc. to ASTM E112. E:Reeled/Skin Pass 3.PED & AD2000-Merkblatt W0/W2/W10 H:Precipitation Hardening 4.DNV . LR . ABS Classification Society certification HR:Hot Rolled 5.ISO14001:2015 Environment Management System I:Straightened 6.ISO45001:2018 & TOSHMS Certificate K:Cut Edge L:Polished 7.EN 10088-5:2009 CPR certification 1. We hereby certify that material described herein has been M:Cold Rolled manufactured and tested with satisfactory results P:Pickled TEST METHOD : S:Shaved in accordance with requirement CHEMICAL-ASTM E1806, E415, E1086, E1019 V:Slit of the above material specification. W:Cut 2. We certify that the material is free from mercury X:Temper and radiation contamination. Qualification CD:Cold Draw CG:Centerless Ground To protect the privacy of customers or No. of Taiwan Atomic Energy Committee: 136 PL:Turned or Peeled 3. The Above Testing Results Relate Only To The Items Tested. suppliers of Salamander Jewelry. 4. No welding repaired We erased their address from this document.