

To protect the privacy of customers or suppliers of Salamander Jewelry.  
We erased their address from this document.

COMMODITY: **Stainless Steel Cold Finished Round Bar**  
CERTIFICATE NO: **A2107310502**

STEEL GRADE: **304**  
DOC No.:

SUPPLY CONDITION: **CD**  
DATE OF ISSUE: **2021/07/31**

ID No	Thick (Dia) (mm)	Pcs	Wt (kg)	Chemical Composition(wt%)													Mechanical Property						
				C x1000	Si x100	Mn x100	P x1000	S x1000	Ni x100	Cr x100	Mo x100	Cu x100	N x10000				TS N/mm2	YS N/mm2	EL %	RA %	HRB	HB	HRC
Spec	Min Max			80	100	200	45	30	800	1800													
6J132113A	18.00	86	1037	63	43	181	27	26.9	808	1822	11	52	717				741	613	46	67	96		

Total: 1037

**ORIGINAL**

TOLERANCE:h9

LENGTH TOLERANCE:0-50

This inspection certificate is issued according to EN 10204 2.2

**Remark:**

Melted and poured in Taiwan , Improved machining.  
Solution annealed treatment:Acc. to ASTM A484.  
Micro structure:good. , Grain size:Acc.to ASTM E112.

**SUPPLY CONDITION:**

A:Annealed  
B:Shot Blasted  
C:As Casted  
E:Reeled/Skin Pass  
H:Precipitation Hardening  
HR:Hot Rolled  
I:Straightened  
K:Cut Edge  
L:Polished  
M:Cold Rolled  
P:Pickled  
S:Shaved  
V:Slit  
W:Cut  
X:Temper  
CD: Cold Draw  
CG: Centerless Ground  
PL: Turned or Peeled

We have the following certifications

- 1.ISO9001:2015 Quality Management System
- 2.ISO/IEC 17025:2017 Laboratory Management System
- 3.PED & AD2000-Merkblatt W0/W2/W10
- 4.DNV 、LR 、 ABS Classification Society certification
- 5.ISO14001:2015 Environment Management System
- 6.ISO45001:2018 & TOSHMS Certificate
- 7.EN 10088-5:2009 CPR certification

**TEST METHOD :**

CHEMICAL-ASTM E1806, E415, E1086, E1019

- 1.We hereby certify that material described herein has been manufactured and tested with satisfactory results in accordance with requirement of the above material specification.
- 2.We certify that the material is free from mercury and radiation contamination. Qualification No. of Taiwan Atomic Energy Committee:136
- 3.The Above Testing Results Relate Only To The Items Tested.
- 4.No welding repaired

To protect the privacy of customers or suppliers of Salamander Jewelry.  
We erased their address from this document.